Tuesday, 11/22/2005 9:50:22 AM Date: Linda Lacelle User: **Process Sheet CU-DAR001** Dart Helicopters Services **Drawing Name** : NUT PLATE ASSEMBLY Cust : 24895B Job Estin Number : 10812 : PIA Part Number : D3178041 P.O. S.O. No. :-NIA : D3178 REV. A : 11/22/2005 **Drawing Number** This : NC Project Number : NA Prsh : N/A : SMALL /MED FAB First Type **Drawing Revision** : VIA : 22409B Material Previ Run Due Date : 12/15/2005 Qty: 4 Um: Each Writte Chec & Approved By Com : Est:B 03.02.28 Modify Step 1,2,3,4,21,23 KJ/RF Addi al Product Job N Machine Or Operation: Description: 1.0 M5052H32S063 5052-H32 .063 Sheet Comment: Oty... 0.1462 sf(s) 0.0365 sf(s)/Unit Total: Material: 5052-H32/H34 (QQ-A-250/8) 0.063" thick Batch: <u>M16454</u> M5052H32S.063) J.G 05/12/09 SHEAR SHEAR 2.0 M5052/1325063 ,88 Comment: SHEAR 5.G oslialog 24 Gut blanks: 3.00" x 1.520" HAAS1 Comment: #AAS CNC VERTICAL MACHINING #1 Machine as per Folio FA296 and Dwg D31 05/12/09 entify as D3178-1 4.0 05/12/09 Comment: INSPECT PARTS AS THEY COME OFF M. QGB Comment: ECOND CHECK

Tuesday 11/22/2005 9:50:23 AM Date Linda Lacelle User! **Process Sheet** Drawing Name: NUT PLATE ASSEMBLY sustomer: CU2DAR001 Dart Helicopters Services Number: 24895B Part Number: D3178041 mber: Description: Machine Or Operation: SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 1 6.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 24 1- C'sink D3178-1 holes as per Dwg D3178 2- Deburr INSPECT WORK TO CURRENT STEP 7.0 QC5 WORK TO CURRENT STEP Comment: HAND FINISHING RESOURCE #1 8.0 Comment: MAND FINISHING RESOURCE #1 chemical Conversion Coat as per QSI 005 4.1 INSPECT POWDER COAT/CHEMICAL CONVERSION 9.0 QC3 Comment: NSPECT CHEMICAL CONVERSION COAT RIVET MS20426AD34 0.0 Comment: Oty.: 32.0000 Each(s) 8.0000 Each(s)/Unit Total: RIVET Pick: 24 Part Number Description MS20426AD3-4 Rivet M\$21059L3 11.0 Comment: Qty.: 4.0000 Each(s)/Unit Total: 16.0000 Each(s) **N**ut Plate Pick: 24 Part Number Description MS21059L3 **Nut Plate** 05-12-19 SMALL FAB 1 12.0 Comment: MALL & MEDIUM FAB RESOURCE 1 24 ssemble as per Dwg D3178


Date Tuesday 11/22/2005 9:50:23 AM User Linda Ladelle **Process Sheet** Drawing Name: NUT PLATE ASSEMBLY customer: CUIDAR001 Dart Helicopters Services Number: 24895B Part Number: D3178041 mber: Description: Machine Or Operation: INSPECT WORK TO CURRENT STEP 13.0 Comment: INSPECT WORK TO CURRENT STEP PACKAGING 1 PACKAGING RESOURCE #1 14.0 Comment: PACKAGING RESOURCE #1 Identify and Stock focation: 402 DOCUMENT CONTROL 5.0 Comment: DOCUMENT CONTROL 05/12/20 inspection Level 21 letion Job (

DM DOT A COL	COACE LTO	The state of the s						
DART AEROSPACE LTD Description:					Work Order:			
					Part Number:			
Inspection Dwg: Rev:						Page 1 of 1		
	FIRS	ST ARTICLE IN	SPECTION	ON CHE	CKLIST	,		
First Article					Prototype			
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments		
2.868	0.010	2.870		3				
1.720	± 0.010	1.721	/					
0.344	010,0t	0.343	/					
1.000	to.010	0,999						
1.460	£0.010	1.462	/					
0 688	10.010	0-686						
0.238	+ 0,005	0.241	V 40					
0.098	10000	0,098	/	Ã				
0~129	10.005	0.131	V					
Ro. 12	1 0.010	RO.12	/					
			٩					

	İ							
						of.		
Measured by	« C	Audited by:	~ ^		ototuno Anna	(2): \/ 2		
Measured by: 5.G		Date: OS(12,04		Prototype Approv				
Date.	05)12109	Date: O.	Date: NA					

Rev	Date	Change	Revised by	Approved
A	,	New Issue	KJ/RF	





NOTES, D3178-1 NUT PLATE:

- 1) PART IS SYMMETRIC ABOUT CENTERLINES
- 2) MATERIAL: 5052-H32/H34 SHEET 0.063 THICK (QQ-A-250/8)

(REF DART SPEC. M5052H32S.063)

- 3) BREAK ALL SHARP EDGES 0.005-0.010
- 4) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- 5) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 6) ALL DIMENSIONS ARE IN INCHES

Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.